T-9-N, R-22-E

RECORD OF SURVEY NO. 31-64

OF THE RIGHT OF WAY OF STATE ROUTE 09-MNO-395, THROUGH PORTIONS OF SECTIONS 2 AND 3, TOWNSHIP 9 NORTH, RANGE 22 EAST, M.D.B.& M. AND SECTIONS 27 AND 34, TOWNSHIP IO NORTH, RANGE 22 EAST, M.D.B. & M. IN THE UNICORPORATED AREA OF THE COUNTY OF MONO. STATE OF CALIFORNIA.

SURVEYOR'S STATEMENT:

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE PROFESSIONAL LAND SURVEYOR'S ACT AT THE REQUEST OF THE CALIFORNIA DEPARTMENT OF TRANSPORTATION IN JULY 2013.

BRIAN L. JARED L.S. 6620



COUNTY SURVEYOR'S STATEMENT:

THIS MAP HAS BEEN EXAMINED IN ACCORDANCE WITH SECTION 8766 OF THE PROFESSIONAL LAND SURVEYOR'S ACT THIS DAY OF APRIL 2014


BRETT K. JEFFERSON MONO COUNTY SURVEYOR



RECORDER'S STATEMENT:

FILED THIS 4th DAY OF APRIL 2014. IN BOOK 5 OF RECORD OF SURVEY MAPS AT PAGES 29-29G AT THE REQUEST OF THE CALIFORNIA DEPARTMENT OF TRANSPORTATION. INSTRUMENT NO: 2014001232 FEE: \$0.00

LYNDA ROBERTS MONO COUNTY RECORDER



BASIS OF BEARING:

1983(1991.35), ZONE 3. BEARING NORTH 49°01'35" WEST, BETWEEN STATE LINE MONUMENT

UTILIZING CALIFORNIA H.P.G.N. POINTS "ROUND MTN" PID: JRI281 AND "BRIDGEPORT" PID: JR0751

VICINITY MAP

NO. 24. AND STATE LINE MONUMENT NO. 23. SAID LINE BEING THE CALIFORNIA/NEVADA

AS A BASELINE. A DIAGRAM DEPICTING THE BASIS OF BEARING IS SHOWN ON SHEET 2.

BORDER. THE COORDINATES OF SAID POINTS WERE ESTABLISHED BY A G.P.S. SURVEY

THE BASIS OF BEARING FOR THIS SURVEY IS THE CALIFORNIA COORDINATE SYSTEM

PURPOSE OF SURVEY:

THIS RECORD OF SURVEY IS BEING FILED TO DOCUMENT THE CORRECT LOCATION OF EXISTING RIGHT OF WAY LINES AND THE ESTABLISHMENT AND MONUMENTATION OF NEW RIGHT OF WAY LINES LINES ALONG THE RIGHT OF WAY OF STATE HIGHWAY ROUTE 09-MNO-395.

NOTES:

COORDINATES AND BEARINGS ARE ON CCS 83(1991.35). ZONE 3. DISTANCES AND STATIONING ARE GRID DISTANCES. DIVIDE BY C.G.F. TO OBTAIN GROUND EQUIVALENT DISTANCES. THE RIGHT OF WAY SHOWN ON THIS SHEET WAS DERIVED FROM PAVEMENT SPLITS AND RECORD R/W CURVE RADII. THERE WERE INSUFFICIENT "C" MONUMENTS AVAILABLE TO DETERMINE A BEST-FIT CENTERLINE. THE DEEDED RIGHT OF WAY RECORD DOES NOT FIT THE AS-BUILT HIGHWAY NOR THE EXISTING R/W MONUMENTS.